


Sound Logic Spindle Speed Control

Rev 2

The spindle speed control accepts step and direction signals from Mach2 and converts the step signals to a 0 to 5 volt or 0 to 10 volt analog (DC) signal for driving a VFD, or DC motor drive.

Warning VFDs analog in ground is not at earth potential, in fact it is often greater than 300 volts. The spindle speed control board uses an isolated power supply and an analog optical isolator to provide the necessary safety for the installer and operators well protecting the electronics.



Set up and Adjustment:

Do not connect the spindle speed control board to the breakout board while power is applied to the breakout board.

The first thing to do is configure Mach2 to provide the step and direction signals on the proper pins. Mach2 also needs to be setup to output the step frequency range.

Refer to the screen shots to configure Mach2. Spindle speed screen snapshots are available for download.

Here are some of the important settings.

Ports and Pins / Port setup and Axis Selection: Put a check in the box for “**Spindle Axis Enabled** (step and direction)”.

The screenshot shows the Mach2 configuration window with the following settings:

- Port Setup and Axis Selection** (selected tab)
- Port #1**: Port Enabled, Port Address: 0x378, Entry in Hex 0-9 A-F only
- Port #2**: Port Enabled, Port Address: 0x0, Entry in Hex 0-9 A-F only
- USB MODE**: USB Mode Enabled, Number of Inputs: 16, Number of Outputs: 16, Program restart necessary, USB Drivers must be loaded for this mode
- Axis Selection**: X Axis Enabled, Y Axis Enabled, Z Axis Enabled, A Axis Enabled, B Axis Enabled, C Axis Enabled, Spindle Axis Enabled (Step / Direction), PWM Control
- MaxNC Mode**: Max CL Mode enabled, Program restart necessary
- Kernel Speed**: 25000Hz, 35000Hz, 45000Hz (selected)

Additional text in the window: "Port pins 2-9 and 1,14,16 and 17 are Outputs", "Pins 10 - 13 , 15 are inputs. There are 12 Inputs and 5 Outputs per port", "OR", "OR", "OR".

Output pins: Spindle Step set to active low, port 1 and pin 1.
 Spindle Dir set to active low, port 1 and pin 14.

Port Setup and Axis Selection | Input Emulation | Input Signals | Input Pins | Output Signals | Output Pins | Encoder Pins

Note: Signals not selected in the "Output Signals" tab are greyed out.

Active Low	Port #	Pin #	Active Low	Port#	Pin#	Active Low	Port#	Pin#
<input type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	1	2	<input type="checkbox"/>	0	0
<input type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	1	6	Charge Pump Safety	1	17
<input type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	1	3	Charge Pump #2	2	17
<input type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	1	7			
<input type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	1	4			
<input type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	1	8			
<input type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	1	5			
<input type="checkbox"/>	1	16	<input checked="" type="checkbox"/>	1	9			
<input type="checkbox"/>	2	1	<input type="checkbox"/>	0	0			
<input type="checkbox"/>	2	14	<input type="checkbox"/>	0	0			
<input type="checkbox"/>	2	16	<input type="checkbox"/>	0	0			
<input checked="" type="checkbox"/>	1	1	<input type="checkbox"/>	0	0			
<input checked="" type="checkbox"/>	1	14	<input type="checkbox"/>	0	0			

Checking an "Active Low" box indicates the signal is active when low. (0VDC)

Printer Ports: Pin numbers must be one of 1,2,3,4,5,6,7,8,9,14,16,17

USB: If using USB Mode, Enter the Input number in the Pin# data box. Port numbers will be ignored.

OK Cancel Apply

NOTE: The first two outputs are being used for the spindle speed control. This leaves you with one relay output plus the charge pump relay output.

Motor Tuning: Click on the Spindle option and set the Velocity to 1000 and the steps per unit to 9. The acceleration can be set to 5000. The minimum Pulse width to 1 and the Direction PreChange to 0.

Motors Setup Velocity/Acceleration

Current Units = Inches

Velocity: 9 Units/Sec

Spindle

X-Axis

Y-Axis

Z-Axis

A / U -Axis

B / V -Axis

C / W -Axis

Steps per Unit: 1000

Current Axis = Spindle

SAVE AXIS TUNING

Use sliders to adjust for optimum Maximum speed performance. During Tuning use the UP and DOWN arrows keys to move axis.


Accel: 316.05 Units/Sec^2

Minimum Pulse Width: 12 uSec (Danger of Lockup)

Direction PreChange: 6 uSec (If set greater than 15)

OK Cancel

On the Logic Configuration page select Pulley Ratio # 4 and set the value to 3600. You may also want to set up one of the other pulley Ratios for your top speed.



Once Mach2 is configured make sure the power is **off to the breakout board**.

1. Connect the cable provided with the spindle speed control to the breakout board and the spindle speed control board.

Do not connect the motor drive at this time.

2. Enter the Pulley Ratio four value into Mach2 spindle speed RPM DRO and press enter. (run screen shot). The example shows **3600**. For testing we used 3600. Once the spindle speed board it checked out and calibrated you can use a different spindle speed in Ratio 4 or set your maximum speed in another pulley speed and then make that pulley your current pulley.

3. Apply **power** to the breakout board. The Charge pump LED should come on.

4. Clip the ground lead of your volt meter to TP7 and the plus lead to Tp8.

5. Click on the **Spindle Button** on the Mach2 screen . The output 1 Led should come on.

6. Adjust VR3 for +5.00 vdc. If it doesn't adjust, make sure that your are adjusting Vr3.

. Warning VFDs analog in ground is not at earth potential Makes sure the VFD is disconnected.

7. Move the meter ground probe to Tp2
8. Move the plus probe to TP1 to verify +12
9. connect the Plus probe to TP3 and adjust VR4 for +5.00vdc.
10. Move the plus probe to TP4 and adjust VR1 (Gain) for +5 vdc or +10 vdc which ever you drive requires.
11. Change the spindle speed DRO to 1800 and press enter.
12. the output will go to ½ the value of step 10.
13. Change the spindle speed DRO to 100 and press enter
14. you will see the activity LED blinking.
15. Adjust VR2 full CW then CCW until the Run relay energizes Use an ohm meter between the center connector (COM) and NC on the RUN relay K1. It will show continuity when the RUN relay energizes. This sets the low speed cutoff. It can be set at the lowest speed you can safely run the motor. The motor will run much hotter at low speeds so keep this in mind when you adjust it. It can also be controlled in Mach2/config/logic/ low speed %.
16. This completes the set up and adjustments.

The drive has high voltage at the connection points so **BE CAREFUL!!!**

Power every thing down, computer, breakout board and the VFD for safety.

Connecting the drive:

The drive has high voltage at the connection points so **BE CAREFUL** and remove power from the drive!!!

There are more than one way that manufactures set there VFDs up.

The analog is simple, just connect the SPD output of the spindle speed board to the analog input of the drive. The GND will connect to the analog ground.

The direction and start/runs is where the difference is.

Some drives start as soon as they receive a direction signal , normally a FWD and REV input to the drive. Others you set the direction with the FWD and REV input that give a start/run signal.

If your drive starts to run when the direction signals are applied, install the jumper JP1 on the spindle speed control PCB. The board is normally shipped with the jumper installed.

Connections:

DIR terminal block

NC to Fwd of the drive

NO to REV of the drive

LEAVE COM OPEN. The ground to your drive will come from the Com screw terminal on the Run terminal block. Internally the Com terminal on the Dir terminal block is connected to the normally open terminal on the Run terminal block.

The Run terminal block

NC in open

NO to start or Run input to the drive

Com to the GND input of the drive

If your drive requires the start/run signal as well as the direction signal

Remove Jumper JP1 on the spindle speed control board. (place it on one of the pins to keep it with the drive PC board.

Connections:

DIR terminal block:

NC to Fwd of the drive

NO to REV of the drive

Com to the GND input of the drive

The **Run** terminal block:

NC in open

NO to start or Run input to the drive

Com to the GND input of the drive

If you find another configuration please let me know and we will help you get it wired.

The Sound Logic Spindle Speed board can be used with other breakout boards.

NOTE: The spindle speed board can be run from any breakout board that can supply power (15 to 24 VDC) to J6 and step and direction signals to J4.

External power:

J6 + = 15 to 24vdc

- = ground

External step and dir signals:

J4

Step Parallel

Gnd Parallel port ground

Dir Parallel