

Aerospace TB3-axis drive board HY-TB3DV-N Instructions

Thank you for choosing our products better and faster operational numerical control for you, please read this manual

Products Features :

1: Integrated SCM manual control system, you can directly from the computer manual

2: The maximum 3.5A drive current to a maximum 86 stepper motor drives, more powerful

3: 1-16 sub-setting, higher accuracy, smoother operation

4 : Overload over-current over-temperature protection, full protection of your computer and peripheral equipment

5: 4 files current settings can be set according to the user the actual current requirement

6: Full closed-type optical isolation to protect the user's computer and equipment

7: Professional design, two-stage signal processing, super anti-jamming

8: Bipolar constant current chopper drive motor low-speed non-creeping phenomenon, noise, non-resonant region.

9: 2-way output control, scalable fifth axis or 2-way control of external equipment.

10: Four input control, you can set limit, emergency stop, which is divided into pairs of knives.


Electrical properties (ambient temperature $T_j = 25\text{ }^\circ\text{C}$ pm):

| | |
|-----------------------------------|---|
| Input Power | 12 - 36V DC power supply |
| Stepper motor drive current | 3A (peak value 3.5A) |
| Drive type | Double-pole constant flow PWM actuation output. |
| Actuates the electrical machinery | 42,57,86 step-by-step the electrical machinery, 2 - 4 (4 6 8 step-by-step electrical machinery) |


Segmentation set table:

| Segmentation set | SW1 | SW2 | Buffer set | SW3 | SW4 | Current set | SW5 | SW6 |
|------------------|-----|-----|------------|-----|-----|-------------|-----|-----|
| Full Step | ON | ON | Fast | ON | ON | 100% | ON | ON |
| Half-step | ON | OFF | 25% | ON | OFF | 75% | ON | OFF |
| 1/8step | OFF | OFF | 50% | OFF | ON | 50% | OFF | ON |
| 1/16step | OFF | ON | Slow | OFF | OFF | 25% | OFF | OFF |

Power output interface function



Detailed map interface marked



Please note the following before the test items

- 1, To determine the size of the supply voltage and current
- 2, Determine the stepper motor power and current (model)
- 3, Determine the stepper motor wiring
- 4, Power Please take 12 ~ 36V 8A (stepper motor in accordance with the work of current matching) The above switching power supply, I received a map indicating the power input interface.

12V power output for a 12V cooling fan to pick up where.

The definition of 1-PIN 25 of Parallel Interface is described as follows:

| PIN14 | PIN7 | PIN6 | PIN5 | PIN7 | PIN1 | PIN2 | PIN7 | PIN4 | PIN3 | PIN8 | PIN9 | PIN16 | PIN17 |
|---------------|--------------|----------|-----------|--------------|----------|-----------|--------------|----------|-----------|-------------------|-------------------|-------------------|-------------------|
| spindle motor | X Empower | X Dir | X Step | Y Empower | Y Dir | Y Step | Z Empower | Z Dir | Z Step | Expanded output 1 | Expanded output 2 | Expanded output 3 | Expanded output 4 |

The definition of 1-PIN15 of Manual Interface is described as follow (Click the image to upper right for the P1 left P15)

| | | | | | | | | | | | | | | |
|--------|--------|-------|-------|----------|---------|----------|----------|-------|-----------|--------|--------|--------|--------|------|
| P1 | P2 | P3 | P4 | P5 | P6 | P7 | P8 | P9 | P10 | P11 | P12 | P13 | P14 | P15 |
| Y Step | X Step | Y Dir | Z Dir | Inp ut 1 | Inp ut2 | Inp ut 3 | Inp ut 4 | X Dir | Emp owe r | Z Step | 5V vdd | Emp ty | Emp ty | GN D |

Limit Switch Description

| | | | |
|----------------------------|----------------------------|----------------------------|----------------------------|
| Input 1 | Input 2 | Input 3 | Input 4 |
| Corresponding parallel P10 | Corresponding parallel P11 | Corresponding parallel P12 | Corresponding parallel P13 |

Output Interface Definition:

| | | | | | | | | | | | | | | | | |
|------|------|------|-----|------|-----|------|-----|------|-----|------|-----|-----|-----|--------|------|------|
| P1 | P2 | P3 | P4 | P5 | P6 | P7 | P8 | P9 | P10 | P11 | P12 | P13 | P14 | P15 | P16 | P17 |
| VD D | GN D | XA + | XA- | XB + | XB- | YA + | YA- | YB + | YB- | ZA + | ZA- | ZB+ | ZB- | MO /V+ | GN D | MO - |

Instructions of MACH




图 1

Open MACH3 software, select mach3MILL, and then click OK. Please refer to Fig.1




图 2

The interface of *MACH3* is displayed as Fig.2. The frequently-used action buttons are listed on the interface. We can configure *MACH* software at first.




图 3

Click *PORT & PIN* sub-menu of *config* menu. Please refer to Fig.3.

Please refer to Fig.4




图 4

To set up the basic frequency within the above Circle 1. This parameter will affect the rotational speed of the motor. After the setup of basic frequency, select Circle 2 where *Configuration Scripting* will be defined, please refer to Fig.5.




图 5

To modify the software settings according to the definition of Parallel Interface which is detailed in the above circle.




图 6

Then select the *output signals* column, as shown in Fig.6, and set up the corresponding items per the setup described in the circle.




图 7

After all have been set up, open the *G CODE* that needs to run, as shown in Fig.7




图 8




图 9

After *G CODE* has been opened, you may see the red button *RESET* flashing. Click *RESET* to stop the flashing and then press *CYCLESTART* at the location of Circle 2.

Note: If you press *TAB* on the keyboard, a manual test panel will be displayed.

The limit interface shall be connected with three-axis limit switch. The setting shall be done in *output signals* column.

