


X1  
 X2  
 GND  
 +5V  
 Y1  
 Y2  
 Z1  
 Z2

+ (12. - 45;



Defaultwerte sind in [Klammern] angegeben!

# X-Achse

TITLE: steppdr v 3D-Steppdriver


Document Number:

Created by: T. Ostermann

Date: 09.07.2000 12:44:30

REV: 2.5

Sheet: 1/5



# Y-Achse

TITLE: steppdr v 3D-Steppdriver


Document Number:

Created by: T. Ostermann

Date: 04.04.2000 19:54:48

REV: 2.5

Sheet: 2/5



# Z-Achse

TITLE: stepdrv 3D-Stepdriver


Document Number:

Created by: T. Ostermann


Date: 04.04.2000 19:54:48

REV: 2.5


Sheet: 3/5



U-Ref	
TITLE: steppdr v 3D-Steppdriver	
Document Number:	
Created by: T. Ostermann	
Date: 02.05.2000 09:01:16	
REV: 2.5	
Sheet: 4/5	



Alle Schalter Oeffner nach GND



# Connections

TITLE: stepdrv 3D-Stepdriver

Document Number:

Created by: T. Ostermann

Date: 02.05.2000 09:01:16

REV: 2.5

Sheet: 5/5